

**St. Stephen's Episcopal Church – Richmond, Virginia**  
**Aeolian-Skinner Organ, Opus 1110, 1951, \*1968**

**Great** 61 notes  
 Quintaton 16  
 Principal 8  
 Spitzflöte 8  
 Bourdon 8  
 Principal 4  
 Rohrflöte 4  
 Twelfth 2-2/3  
 Fifteenth 2  
 Fourniture IV  
 Cymbale II-III\*  
 Trompette de Fête 8\*  
 Clairon de Fête 4\*  
 Chimes

**Swell** 61 notes  
 Geigen Principal 8  
 Stopped Diapason 8  
 Viole de Gambe 8  
 Viole Céleste 8  
 Flûte Céleste 8 II  
 Principal 4  
 Flauto Traverso 4  
 Octavin 2\*  
 Plein Jeu IV  
 Contre Hautbois 16  
 Trompette 8  
 Hautbois 8  
 Clairon 4  
 Tremulant

**Choir** 61 notes  
 Singend Gedackt 8  
 Viola 8  
 Viola Céleste 8  
 Erzähler 8  
 Kleiner Erzähler 8  
 Koppelflöte 4  
 Nasard 2-2/3  
 Blockflöte 2  
 Tierce 1-3/5  
 Clarinet 8  
 Tremulant

**Positiv** 61 notes  
 Holzgedackt 8\*  
 Prinzpal 4\*  
 Spillflöte 4\*  
 Lieblich Prinzpal 2\*  
 Larigot 1-1/3\*  
 Siffelöte 1\*  
 Scharf III\*

**Pedal** 32 notes  
 Principal Bass 16  
 Quintaton 16 (Gt.)  
 Bourdon 16  
 Echo Lieblich 16 (Sw.)  
 Principal 8  
 Flûte 8 (ext. Bourdon)  
 Super Octave 4  
 Spitzflöte 4\*  
 Mixture IV\*  
 Contre Bombarde 32\*  
 Bombarde 16  
 Hautbois 16 (Sw.)  
 Trompette 8  
 Clairon 4  
 Cymbelstern

**Antiphonal\***  
 8 Principal 8  
 4 Praestant 4  
 2 Flachflöte 2  
 Mixture IV-VI  
 Trompette de Fête 8\* (Gt.)  
 Clairon de Fête 4\* (Gt.)

**Antiphonal Pedal\***  
 Principal 16

The main part of the organ is located behind the facade on the Gospel side of the chancel and was built in 1951 by the Aeolian-Skinner Organ Company of Boston. It was designed by and installed under the supervision of G. Donald Harrison, president and tonal director of the company until his death in 1956. In 1968 Aeolian-Skinner made additions (denoted by asterisks \* above) that included the Antiphonal Organ flanking the Patriots window on the west wall, the Positiv Organ on the Epistle side of the chancel, several new ranks in the main organ, and a new four manual console. The entire organ was cleaned and re-leathered in 2004 by Emery Brothers of Quakertown, Pennsylvania, caretakers of the organ since 1985. In 2005 the original combination action was disconnected but left in place, and a new solid-state, multilevel combination action was installed by Walker Technical Company. The organ and console were refurbished during 2015 by Emery Brothers.